

1A. Cost Center:		<b>TAT ZONE II CONTRACT</b> <b>CONTRACT NO. 68-01-7368</b> <b>TECHNICAL DIRECTION DOCUMENT (TDD)</b> <b>ECOLOGY AND ENVIRONMENT, INC.</b>			2. No.: T					
1B. Account No.:					Amendment _____					
3A. Priority <input checked="" type="checkbox"/> High <input type="checkbox"/> Medium <input type="checkbox"/> Low		4A. Estimate of Total Hours: 200 Total Costs:		5A. EPA Site Name: <u>Taylor Way Drums Removal</u>		7. CERCLIS ID:				
3B. Key EPA Contact: Name: <u>Cutler</u> Phone: <u>442-1263</u>		4B. Over-time Approved: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	4C. Non-dedicated Approved: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	5B. SSID No.: <input checked="" type="checkbox"/> CERCLA <input type="checkbox"/> 311 <input type="checkbox"/> UST	5C. City/County/State: <u>Tacoma/Pierce/WA</u>					
				6. Source of Funds: <input type="checkbox"/> Other _____		8. Completion Date: <u>9/30/90</u> <del>8/30/90</del>				
						8A. Reference Info: <input type="checkbox"/> Yes <input type="checkbox"/> Attached <input checked="" type="checkbox"/> No <input type="checkbox"/> Pick-up				
9. Type of Activity: <table style="width:100%; border: none;"> <tr> <td style="width:33%; vertical-align: top;"> <u>CWA-311</u>  <input type="checkbox"/> SPCC  <input type="checkbox"/> On-Scene Monitoring  <input type="checkbox"/> Spill Clean-up Funded                 </td> <td style="width:33%; vertical-align: top;"> <u>CERCLA</u>  <input checked="" type="checkbox"/> Site Assessment  <input type="checkbox"/> Removal Funded  <input type="checkbox"/> Removal PRP (AO/CO)  <input type="checkbox"/> On-Site Monitoring                 </td> <td style="width:33%; vertical-align: top;"> <u>AS SPECIFIED ABOVE</u>  <input type="checkbox"/> Special Project  <input type="checkbox"/> Analytical Project  <input type="checkbox"/> Preparedness  <input type="checkbox"/> UST  <input type="checkbox"/> FEMA                 </td> <td style="width:33%; vertical-align: top;"> <input type="checkbox"/> Quality Assurance  <input type="checkbox"/> Training  <input type="checkbox"/> Program Management  <input type="checkbox"/> Technical Assistance  <input type="checkbox"/> Information Management                 </td> </tr> </table>							<u>CWA-311</u> <input type="checkbox"/> SPCC <input type="checkbox"/> On-Scene Monitoring <input type="checkbox"/> Spill Clean-up Funded	<u>CERCLA</u> <input checked="" type="checkbox"/> Site Assessment <input type="checkbox"/> Removal Funded <input type="checkbox"/> Removal PRP (AO/CO) <input type="checkbox"/> On-Site Monitoring	<u>AS SPECIFIED ABOVE</u> <input type="checkbox"/> Special Project <input type="checkbox"/> Analytical Project <input type="checkbox"/> Preparedness <input type="checkbox"/> UST <input type="checkbox"/> FEMA	<input type="checkbox"/> Quality Assurance <input type="checkbox"/> Training <input type="checkbox"/> Program Management <input type="checkbox"/> Technical Assistance <input type="checkbox"/> Information Management
<u>CWA-311</u> <input type="checkbox"/> SPCC <input type="checkbox"/> On-Scene Monitoring <input type="checkbox"/> Spill Clean-up Funded	<u>CERCLA</u> <input checked="" type="checkbox"/> Site Assessment <input type="checkbox"/> Removal Funded <input type="checkbox"/> Removal PRP (AO/CO) <input type="checkbox"/> On-Site Monitoring	<u>AS SPECIFIED ABOVE</u> <input type="checkbox"/> Special Project <input type="checkbox"/> Analytical Project <input type="checkbox"/> Preparedness <input type="checkbox"/> UST <input type="checkbox"/> FEMA	<input type="checkbox"/> Quality Assurance <input type="checkbox"/> Training <input type="checkbox"/> Program Management <input type="checkbox"/> Technical Assistance <input type="checkbox"/> Information Management							
10. General Task Description: <u>Evaluate 2146 Taylor Way site for removal potential</u>						11. Desired Report Form: <input checked="" type="checkbox"/> Formal Report <input type="checkbox"/> Letter Report <input type="checkbox"/> Formal Briefing <input type="checkbox"/> Other (Specify) _____				
12. Specific Elements: <u>(1) Reported abandoned drums (34 count to date) were observed in the dirt basement of Superlawn Plastics warehouse, formerly owned by Justis Cedar Homes (now Lyndal Cedar Homes). Contact Don Richards, Manager, Superlawn Plastics (383 5877 for access.</u> <u>(2) Evaluate the site for removal potential and sample as necessary.</u> <u>(3) Deliverables include: a site safety plan; work plan, including nature of problem, sampling, attain site access, interview with PRP, photo and logbook documentation.</u> <u>(4) Generate formal report and drafts of selected data as needed by OSC.</u> <u>(5) Other activities as directed by OSC.</u>						13. Interim Deadlines:  <u>(3) <del>8/10/90</del> 9/14/90</u>  <u>(4) <del>8/22/90</del> 9/28/90</u>				
14. Authorizing DPO: _____ <div style="text-align: right;">(Signature)</div>						15. Date: <u>7/30/90</u>				
16. Received by: <input type="checkbox"/> Accepted <input type="checkbox"/> Accepted with Exceptions (Attached) <input type="checkbox"/> Rejected _____ <div style="text-align: right;">(TATL Signature)</div>						17. Date:				

Distribution:

Sheet 1 White	- DPO Copy	
Sheet 2 Blue	- TATL Copy	
Sheet 3 Green	- ZPM Copy	
Sheet 4 Canary	- PO Copy	
Sheet 5 Pink	- CO Copy	
Sheet 6 Goldenrod	- DPO Original (Unsigned by TATL)	

USEPA SF



1473115